P50

Automatic positioning system
the fast moving pusher reaches a maximum
cistance of 60m/min with perfect positioning

Optional equipment
Auto tracer
a fluorescent pen is used to mark off unwanted
marks on the material which is later cut off with
the aid of a sensor.

This section is acted as auto defect
cutting program.
To use the fluorescent crayon marked
the front & back of defect parts for
cutting line.

This section It can also to set one desire
d cutting size between the defect parts
automatically